

TECHZHUAL SUPPORT 2014

PHENIX WEEKLY PLANNING



March 27, 2014 Don Lynch




PH*ENIX

This Week

Run 14 Continues No Access this week:

- Plan for 2014 Shutdown
- Tech Support for Run 14 as required
- Support for sPHENIX efforts as required





THUHZHUAL SUPPORT NO14

Next Week

- Run 14 Continues
- Next Access 4/2?
 - Install MPC-Ex FEM Other IR maintenance/repairs
- Plan for 2014 Shutdown
- Tech Support for Run 14 as required
- sPHENIX Review
- Support for sPHENIX efforts as required


3/27/2014




MPC-Ex Initial (Partial) Installation

-ECHZHUAL SUPPORT

2014







Mechanical installation Complete Services connected


FEM assembly waiting for final FEM modules


New MPC-Ex rack




FECHZHUAL SUPPORT NO14

sPHENIX Overall Detector Design Concept







March 27, 2014

sPHENIX Mechanical Design



THUHZHUAL SUPPORT 2014

Weights by Carriage ("Outie")

Model v1

Weight of West Carriage 733,101 lb

Carriage 250,000 lb 135 degree of HCal 483,101 lb

Weight Of Central Pedestal 484,462 lb

 Carriage
 75,000 lb

 90 degree of HCal
 322,067 lb

 Magnet
 30,865 lb

 EMCal
 44,730 lb

 VTX
 800 lb

 EMCal Support Structure
 10,000 lb

 VTX Support Structure
 1,000 lb

Weight of West Carriage 733,101 lb

Carriage 250,000 lb 135 degree of HCal 483,101 lb

Total Wt 1,950,664



TECHZHCAL SUPPORT

Weights by Carriage ("Innie")

Model v2

Weight of West Carriage 476,058 lb

Carriage 250,000 lb 135 degree of Outer HCal 226,058 lb

Weight Of Central Pedestal 297,834 lb

Carriage 75,000 lb 90 degree of Outer HCal 150,706 lb 30,865 lb Magnet 29,464 lb **EMCal** VTX 800 lb **EMCal Support Structure** 10,000 lb **VTX Support Structure** 1,000 lb Inner HCal 85,792 lb

Weight of West Carriage 476,058 lb


Carriage 250,000 lb 135 degree of HCal 226,058 lb


Total Wt 1,249,951




FECHZHUAL SUPPORT

ePHENIX







3/27/2014

Plan View

10



2014 planned Technical Support & 2014 Shutdown

	· · · · · · · · · · · · · · · · · · ·	
LECHZHOAT	Support for run 14 Support for sPHENIX prototype tests at FermiLab Procure & Fabricate parts for MPC-Ex North and South Assemble & test MPC-Ex South, ready for installation End of Run Party Assemble & test MPC-Ex North, ready for installation Start of Shutdown Tasks (purge flammable gas, disassemble and	2/3-6/30/2014 1/21-2/25/2014 1/1/2014-6/30/2014 3/1-7/1/2014 7/11/14? 7/1-9/25/2014
C	stow shield wall, remove collars, move EC to AH, Move MMS south, etc.) Remove MMS east vertical lampshade	7/14 - 7/25/2014 7/28-7/30/2014
A	Troubleshoot intermittent water leak in MMS	7/30-8/8/2014
	Other Maint. In MMS	TBD
	Reinstall MMS east vertical lampshade	TBD
C	Summer Sunday prep AH, tours and restore AH	7/30-8/15/2014
3	Install scaffolding in Sta 1 South	7/28/2014
U	Remove MPC-Ex prototype, Install new MPC-Ex South	7/28-8/22/2014
SUPPORT	Maint. & Repairs for MPC South, BBC South, RPC1 South, MuTr sta 1	_,,
Ь	South, as necessary	7/28-8/22/2014
5	Remove scaffolding from sta 1 south, Move CM South	8/25/2014
Q	Install scaffolding in Sta 1 North	8/26-8/29/2014
R	Prep MPC-Ex North installation area	9/1-9/26/2014
Ť	Install new MPC-Ex North	9/29-10/17/2014
•	Remove Sta 1 North scaffolds, Move CM North	10/20-10/24/2014
	Other detector support	TBD
2	Infrastructure Maintenance and Improvement	TBD
0	Decommissioning of obsolete PHENIX detector equipment	TBD
2 0 1 4	SPHENIX Support	on-going
4	End of Shutdown Tasks (Move MS north, roll in EC, install collars,	10/27-11/26/2014
4	remove 10 ton cart, plates and manlifts, build shield wall, etc.) Pink/White/Blue Sheets	1/17/2014
	End of Shutdown Party	5555
	Start Flammable gas flow Class shield well install radiation interlesks and propers for run 14	???? 12/31/2014
	Close shield wall, install radiation interlocks and prepare for run 14 Start run 15	1/2/2014
	Start ran 19	1/2/2010

3/27/2014

11

Safety and Security

FRom Ray Karol:

From the SBMS on use of Government Vehicles - pay attention to this requirement as the BNL Police are looking for these violations:

"Do not leave a parked vehicle with the engine running (except where specified for police or emergency vehicles), or with the ignition key in it"


- Work Control Coordinator's Meeting Yesterday with Mike Zarcone.
 - Work Permit update
 - Working Alone Guidance (PHENIX has the "2-man rule")

3/27/2014

PHENIX Safety and Security

TECHZHUAL SUPPORT 2014





Injury Status:

FY14 YTD: DART - 8, TRC - 17, First Aid - 23 FY13: DART - 15, TRC - 38, First Aid - 53

FY12: DART - 19, TRC - 36, First Aid - 69

FY13 Injury Listing: https://intranet.bnl.gov/esh/shsd/seg/Occlnj/BNLInjuries.aspx

Recent Injuries							
		None					





FUCHZHUAL SUPPORT NO14

Recent Events				
3/20/14	Non- Reportable	On March 20, approximately 25 gallons of oil were found on the floor of the pit for the Westinghouse motor-generator (MG) set in Building 911. The MG set powers the AGS magnets and the pit houses the lubricating oil system. A small leak on the pressure gauge was found to be the source of the spilled oil. The MG set was turned off and the gauge was replaced. Cleanup of the oil is in progress. The Collider-Accelerator Department (C-AD) Environmental Compliance Representative was informed and New York State (NYS) was notified via routine report. The oil was contained in the pit as designed and there was no impact to the environment. (Event Link)		
3/18/14	Non- Reportable	A Facility Project Manager (FPM) responded to a report of a non-functioning electric baseboard heater in Building 130, Room 2-35. The FPM confirmed that there was no heat and identified a tripped breaker in the service panel. The FPM donned appropriate Personal Protective Equipment (PPE) for a 0+ designated panel and reset the breaker. When the FPM returned to the room and turned the control dial to allow heat, the electric baseboard sparked briefly (a few seconds and stopped). A BNL electrician was called to the building and a yellow tag was applied to the breaker. The occupant was provided with a portable electric heater. At approximately 1500, the Fire Captain was informed of the situation. At approximately 1515, the Central Complex ESH Representative and Facility Complex Manager were also informed. There was no shock associated with this event. (Event Link)		
3/13/14	SC-BNL	An employee was driving a government vehicle near Building 326 when the vehicle suddenly stalled. There were no warning lights on the dash. He attempted to restart the vehicle when he noticed smoke coming from under the hood. He retrieved the vehicle-mounted fire extinguisher and extinguished the small under-hood fire. He then contacted Fire-Rescue to respond. Based upon investigation, it appears that the starter solenoid shorted out and caused the wires and terminals to overheat and ignite. Damage was limited to the cable and starter motor assembly. The auto shop mechanics are replacing the starter and burned wires. (Event Link)		





Where To Find PHENIX Engineering Info

Run 14 Continues!



New Addition to PHENIX Mild Hogs